

VEILIG GEBRUIK VAN ZZS

ARTIKEL 33 VAN DE REACH-VERORDENING BETREFFENDE ZEER ZORGWEKKENDE STOFFEN

Beste klant,

De REACH-verordening (EG) nr. 1907/2006, artikel 33 (1) dient om klanten van geleverde producten de mogelijkheid te geven om alle relevante risicobeheermaatregelen te nemen op grond van de aanwezigheid van zeer zorgwekkende stoffen (ZZS) vermeld op de kandidatenlijst voor autorisatie, om op die manier hun veilig gebruik te garanderen.

FORD ondersteunt de algemene onderliggende doelstellingen van REACH en artikel 33(1) in het bijzonder. Die doelstellingen zijn in lijn met onze eigen inzet om de verantwoorde productie, behandeling en gebruik van onze producten te promoten.

Aanduiding van ZZS

Gebaseerd op de ontvangen informatie van onze toeleveringsketen en op onze eigen productgegevens, zijn voor zover wij weten de ZZS die voor meer dan 0,1% m/m in componenten aanwezig zijn, terug te vinden op de relevante "ZZS-lijst" voor het specifieke voertuig/onderdeel.

Specifieke informatie voor het veilige gebruik van artikelen met ZZS

Indien van toepassing wordt specifieke informatie voor het veilige gebruik van artikelen met ZZS toegevoegd aan de relevante "ZZS-lijst" voor het specifieke voertuig/onderdeel.

Algemene informatie voor het veilige gebruik van artikelen

Elk FORD-voertuig bevat een gebruikershandleiding met informatie over veilig gebruik voor eigenaars/bestuurders van het voertuig. De informatie van FORD betreffende de reparatie en het onderhoud van voertuigen en authentieke onderdelen bevat ook informatie over veilig gebruik voor onderhoudspersoneel.

De ZZS die in bepaalde onderdelen van het voertuig aanwezig zijn en op de relevante "ZZS-lijst" voor het specifieke voertuig/onderdeel vermeld worden, zijn in die mate in het voertuig verwerkt dat het mogelijke risico voor de klanten tot een minimum beperkt is en dat het gevaar voor de mens of het milieu onbestaande is zolang het voertuig en de onderdelen gebruikt worden zoals bedoeld en zolang elke reparatie, service en onderhoud uitgevoerd wordt volgens de technische instructies voor dergelijke praktijken en de goede werkwijzen die door de sector worden opgelegd.

Een voertuig aan het einde van zijn levensduur mag wettelijk gezien enkel in de Europese Unie bij een erkende verwerker (ATF) afgevoerd worden.

Voertuigonderdelen moeten afgevoerd worden in overeenstemming met de geldende lokale wetgeving en de lokale richtlijnen van de autoriteiten.

Model: Ford Explorer

ZZS-lijst gebaseerd op de ECHA-kandidatenlijst sinds 1 januari 2026

Specifieke informatie voor het veilige gebruik van artikelen met ZZS

Er is geen specifieke informatie voor veilig gebruik vereist. Volg de algemene informatie voor het veilige gebruik van artikelen.

Commodity	REACH SVHCs
Accessories	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
	Lead [7439-92-1]
Air Induction	Lead [7439-92-1]
Appliques (Pillar, Decklid, Roof)	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	C,C'-azodi(formamide) [123-77-3]
Auto Transmission	Boric acid [10043-35-3]
	Lead [7439-92-1]
Auto Transmission Cooler and Lines	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Auto Transmission Shifter	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Body and Security Electronics	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
	1-Propanol, 2,3-dibromo- [96-13-9]
	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Boric acid [10043-35-3]
	Lead [7439-92-1]
	Melamine [108-78-1]
	TBBA [79-94-7]
Body Side InteriorTrim (Hard Trim)	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Melamine [108-78-1]
Body Structure - Floor Pan - Rear Floor	C,C'-azodi(formamide) [123-77-3]
Body Structure - Front Fender	Dicyclohexyl-phthalate [84-61-7]

Brakes	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Dicyclohexyl-phthalate [84-61-7]
	Lead [7439-92-1]
Bumpers and Spoilers	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Dodecamethylcyclohexasiloxane [540-97-6]
	Lead [7439-92-1]
	TBBA [79-94-7]
Climate	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Cobalt-dinitrate [10141-05-6]
	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
	Tris(nonylphenyl)phosphite [26523-78-4]
Closures and Lids BIW	Lead [7439-92-1]
Closures and Lids Mechanisms	Octamethylcyclotetrasiloxane [556-67-2]
	Triphenyl-phosphate [115-86-6]
Console Floor/Rear	Lead [7439-92-1]
Cooling	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Dressed Engine	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
Driveline	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Driveline (Powerpack)	Boric acid [10043-35-3]
Driver Controls	Lead [7439-92-1]
EDS	Boric acid [10043-35-3]
	Decamethylcyclopentasiloxane [541-02-6]
	Dodecamethylcyclohexasiloxane [540-97-6]
	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
	Tris(2-methoxyethoxy)vinylsilane [1067-53-4]
Exhaust Cold End	Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8]
	Lead [7439-92-1]
Exterior Lighting	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
	Silicic acid, lead salt [11120-22-2]
	TBBA [79-94-7]
Fascia Grille - Radiator	Lead [7439-92-1]
Front / Rear Door Trim	Cobalt-sulfate-heptahydrate [10026-24-1]
	Lead [7439-92-1]
Fuel	Lead [7439-92-1]
Glass Runs and Belts	Bumetrizole [3896-11-5]
	Lead [7439-92-1]

GOR and Radiator Support	Lead [7439-92-1]
Headliner / Sunvisor	Hexahydromethylphthalic-anhydride [25550-51-0]
Hybrid Technology	Lead [7439-92-1]
	Silicic acid, lead salt [11120-22-2]
Interior Trim	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
	Tris(nonylphenyl)phosphite [26523-78-4]
IP and Console	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
IP Finish Panels/Registers	Lead [7439-92-1]
IP Substrate and Ducts	Lead [7439-92-1]
Latches - Hood, Decklid and Liftgate Latches	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Lower Body Structure	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
	C,C'-azodi(formamide) [123-77-3]
Luggage and Interior Cargo Management/Covers	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Mirrors	Lead [7439-92-1]
Multimedia	Boric acid [10043-35-3]
	Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4]
	Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8]
	Lead [7439-92-1]
	Melamine [108-78-1]
	Octamethyltrisiloxane [107-51-7]
Overhead Console	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
Pedals	Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8]
Power Supply	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Cobalt(II) nitrate hexahydrate [10026-22-9]
	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
Powertrain Controls and Calibration	Lead [7439-92-1]
Powertrain Mounts	1-Methyl-2-pyrrolidone [872-50-4]
	Lead [7439-92-1]
Restraint	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Roof	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
Safety Electronics	1,3-Propanesultone [1120-71-4]

	Lead [7439-92-1]
	TBBA [79-94-7]
Seat Belts (Front and Rear)	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
Seating	Lead [7439-92-1]
	Melamine [108-78-1]
	Phenol, dimethyl-, phosphate (3:1) [25155-23-1]
	Sodium borate, decahydrate [1303-96-4]
	Triphenyl-phosphate [115-86-6]
Seats - Foam - Cut and Sew	Triphenyl-phosphate [115-86-6]
Seats - Structures	Lead [7439-92-1]
	N,N-Dimethylacetamide [127-19-5]
	Sodium borate, decahydrate [1303-96-4]
Side Door Mechanisms	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
Spoiler	Lead [7439-92-1]
Static Sealing	C,C'-azodi(formamide) [123-77-3]
Steering	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Suspension Frames and Mountings	Lead [7439-92-1]
Switches	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
	2-Methylimidazole [693-98-1]
	4,4'-Isopropylidenediphenol [80-05-7]
	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
Transmission - Auto	Lead [7439-92-1]
Upper Body Structure	C,C'-azodi(formamide) [123-77-3]
	Triphenyl-phosphate [115-86-6]
Wash-Wipe	Dodecamethylcyclohexasiloxane [540-97-6]
	Lead [7439-92-1]
Wheels Tires Jacks and Equipment	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
	Lead [7439-92-1]
	Melamine [108-78-1]
Window Regulator	Lead [7439-92-1]