

VEILIG GEBRUIK VAN ZZS

ARTIKEL 33 VAN DE REACH-VERORDENING BETREFFENDE ZEER ZORGWEKKENDE STOFFEN

Beste klant,

De REACH-verordening (EG) nr. 1907/2006, artikel 33 (1) dient om klanten van geleverde producten de mogelijkheid te geven om alle relevante risicobeheermaatregelen te nemen op grond van de aanwezigheid van zeer zorgwekkende stoffen (ZZS) vermeld op de kandidatenlijst voor autorisatie, om op die manier hun veilig gebruik te garanderen.

FORD ondersteunt de algemene onderliggende doelstellingen van REACH en artikel 33(1) in het bijzonder. Die doelstellingen zijn in lijn met onze eigen inzet om de verantwoorde productie, behandeling en gebruik van onze producten te promoten.

Aanduiding van ZZS

Gebaseerd op de ontvangen informatie van onze toeleveringsketen en op onze eigen productgegevens, zijn voor zover wij weten de ZZS die voor meer dan 0,1% m/m in componenten aanwezig zijn, terug te vinden op de relevante "ZZS-lijst" voor het specifieke voertuig/onderdeel.

Specifieke informatie voor het veilige gebruik van artikelen met ZZS

Indien van toepassing wordt specifieke informatie voor het veilige gebruik van artikelen met ZZS toegevoegd aan de relevante "ZZS-lijst" voor het specifieke voertuig/onderdeel.

Algemene informatie voor het veilige gebruik van artikelen

Elk FORD-voertuig bevat een gebruikershandleiding met informatie over veilig gebruik voor eigenaars/bestuurders van het voertuig. De informatie van FORD betreffende de reparatie en het onderhoud van voertuigen en authentieke onderdelen bevat ook informatie over veilig gebruik voor onderhoudspersoneel.

De ZZS die in bepaalde onderdelen van het voertuig aanwezig zijn en op de relevante "ZZS-lijst" voor het specifieke voertuig/onderdeel vermeld worden, zijn in die mate in het voertuig verwerkt dat het mogelijke risico voor de klanten tot een minimum beperkt is en dat het gevaar voor de mens of het milieu onbestaande is zolang het voertuig en de onderdelen gebruikt worden zoals bedoeld en zolang elke reparatie, service en onderhoud uitgevoerd wordt volgens de technische instructies voor dergelijke praktijken en de goede werkwijzen die door de sector worden opgelegd.

Een voertuig aan het einde van zijn levensduur mag wettelijk gezien enkel in de Europese Unie bij een erkende verwerker (ATF) afgevoerd worden.

Voertuigonderdelen moeten afgevoerd worden in overeenstemming met de geldende lokale wetgeving en de lokale richtlijnen van de autoriteiten.

Model: Ford Explorer

ZZS-lijst gebaseerd op de ECHA-kandidatenlijst sinds 1 januari 2026

Specifieke informatie voor het veilige gebruik van artikelen met ZZS

Er is geen specifieke informatie voor veilig gebruik vereist. Volg de algemene informatie voor het veilige gebruik van artikelen.

Commodity	REACH SVHCs
Accessories	Bumetrizole [3896-11-5]
	Lead [7439-92-1]
Body and Security Electronics	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
	TBBA [79-94-7]
	Triphenyl-phosphate [115-86-6]
Body Covers and Ornamentation	Bumetrizole [3896-11-5]
Body Side InteriorTrim (Hard Trim)	C,C'-azodi(formamide) [123-77-3]
Brakes	Lead [7439-92-1]
	TBBA [79-94-7]
Bumpers and Spoilers	Diocetyl tin dilaurate [3648-18-8]
	Lead [7439-92-1]
Climate	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
	Melamine [108-78-1]
	TBBA [79-94-7]
Closures and Lids BIW	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Lead [7439-92-1]
Closures and Lids Mechanisms	Lead [7439-92-1]
Coil Spring (Front, Rear)	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Console Floor/Rear	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
Cooling	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Boric acid [10043-35-3]
	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Driver Controls	Lead [7439-92-1]

EDS	1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4]
	Bumetrizole [3896-11-5]
	Decamethylcyclopentasiloxane [541-02-6]
	Dodecamethylcyclohexasiloxane [540-97-6]
	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
	Triphenyl-phosphate [115-86-6]
Electrified Drivetrain Systems	Lead [7439-92-1]
Exterior Lighting	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Fixed Glazing	Bumetrizole [3896-11-5]
Front / Rear Door Trim	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Hybrid Technology	Bumetrizole [3896-11-5]
	Decamethylcyclopentasiloxane [541-02-6]
	Lead [7439-92-1]
I/S Mirror	Lead [7439-92-1]
Interior Trim	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
	Melamine [108-78-1]
	TBBA [79-94-7]
IP Substrate and Ducts	Lead [7439-92-1]
Latches - Hood, Decklid and Liftgate Latches	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Latches - Side Door/Latch Mini Module	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Lead [7439-92-1]
Lower Body Structure	Lead [7439-92-1]
Mirrors	Cyclohexane-1,2-dicarboxylic anhydride [85-42-7]
	Decamethylcyclopentasiloxane [541-02-6]
	Lead [7439-92-1]
	TBBA [79-94-7]
Multimedia	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
Pedals	Lead [7439-92-1]
Power Supply	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	TBBA [79-94-7]

Powertrain Controls and Calibration	Lead [7439-92-1]
Powertrain Mounts	Lead [7439-92-1]
Restraint	Lead [7439-92-1]
Safety Electronics	Lead [7439-92-1]
Seating	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Seats - Foam - Cut and Sew	O,O,O-Triphenyl phosphorothioate [597-82-0]
	Triphenyl-phosphate [115-86-6]
Seats - Structures	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
Shock Absorbers	Lead [7439-92-1]
Side Air Bag (SAB) and Curtain Air Bag (CAB)	Lead [7439-92-1]
Side Door Mechanisms	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Steering	Lead [7439-92-1]
	Phosphorothioic acid, O,O,O-triphenyl esters, tert-Bu derivs. [192268-65-8]
Suspension Frames and Mountings	2-Methylimidazole [693-98-1]
	Bumetrizole [3896-11-5]
	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
Switches	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	4,4'-Isopropylidenediphenol [80-05-7]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Switches - General Use	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
Upper Body Structure	Bumetrizole [3896-11-5]
Wash-Wipe	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
	TBBA [79-94-7]
Wheels Tires Jacks and Equipment	1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4]
	Lead [7439-92-1]